

VTOB108

Surface Mounted Box for VTO2000A



Installation

- a) Install metal bracket into the groove on wall. At spot 1 fasten screw (ST3×18 Cross recessed countersunk head tail tapping screws--- galvanizing white), and fix metal bracket on wall. See Figure 1
- b) Align the device on metal bracket according to screw hole. At spot 2 fasten screw (M3×8 Cross recessed countersunk head tail machine screws--- galvanizing white), and fix device on metal bracket. See Figure 2

Features

Material: Metal

· Size: 145mm*134mm*88mm

· Weight: 1 Kg

· Surface mounted box




Figure 1




Figure 2

